

INTERNATIONAL  
STANDARD

ISO  
23529

Third edition  
2016-11-01

---

---

---

**Rubber — General procedures for  
preparing and conditioning test pieces  
for physical test methods**

*Caoutchouc — Procédures générales pour la préparation et le  
conditionnement des éprouvettes pour les méthodes d'essais physiques*



Reference number  
ISO 23529:2016(E)

© ISO 2016



## **COPYRIGHT PROTECTED DOCUMENT**

© ISO 2016, Published in Switzerland

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized otherwise in any form or by any means, electronic or mechanical, including photocopying, or posting on the internet or an intranet, without prior written permission. Permission can be requested from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office  
Ch. de Blandonnet 8 • CP 401  
CH-1214 Vernier, Geneva, Switzerland  
Tel. +41 22 749 01 11  
Fax +41 22 749 09 47  
[copyright@iso.org](mailto:copyright@iso.org)  
[www.iso.org](http://www.iso.org)

# Contents

	Page
<b>Foreword</b>	<b>v</b>
<b>1 Scope</b>	<b>1</b>
<b>2 Normative references</b>	<b>1</b>
<b>3 Terms and definitions</b>	<b>1</b>
<b>4 Identification and record keeping</b>	<b>1</b>
<b>5 Standard laboratory conditions</b>	<b>2</b>
5.1 Standard laboratory temperature	2
5.2 Standard laboratory humidity	2
5.3 Other conditions	2
<b>6 Storage of samples and test pieces</b>	<b>2</b>
<b>7 Preparation of test pieces</b>	<b>3</b>
7.1 Test piece thickness	3
7.2 Thickness adjustment	3
7.2.1 General	3
7.2.2 Techniques	3
7.2.3 Equipment for test piece preparation	4
7.3 Test piece cutters	5
7.3.1 General	5
7.3.2 Fixed-blade cutters	5
7.3.3 Replaceable-blade cutters	6
7.3.4 Rotary cutters	6
7.4 Maintenance of cutters	6
7.5 Preparation of test pieces by moulding	6
7.5.1 Test sheets	6
7.5.2 Test pieces	6
7.5.3 Thermoplastic materials	6
7.6 Preparation of unvulcanized test pieces	7
<b>8 Conditioning</b>	<b>7</b>
8.1 General	7
8.2 Conditioning times for subnormal or elevated temperatures	7
<b>9 Measurement of the dimensions of test pieces</b>	<b>7</b>
9.1 Method A — For dimensions less than 30 mm	7
9.2 Method B — For dimensions of 30 mm and up to and including 100 mm	8
9.3 Method C — For dimensions over 100 mm	8
9.4 Method D — Non-contact method	8
<b>10 Conditions of test</b>	<b>9</b>
10.1 Duration of test	9
10.2 Temperature and humidity	9
10.2.1 Standard laboratory temperature and humidity	9
10.2.2 Other test temperatures	9
<b>11 Test chambers</b>	<b>10</b>
11.1 General requirements for temperature-controlled chambers	10
11.2 Chambers operating at elevated temperatures	11
11.2.1 Chambers with gaseous heat-transfer media	11
11.2.2 Chambers with liquid heat-transfer media	11
11.2.3 Fluidized beds	11
11.3 Chambers operating at subnormal temperatures	11
11.3.1 Mechanically refrigerated units	11
11.3.2 Solid carbon dioxide units (direct-cooling type)	11
11.3.3 Solid carbon dioxide units (indirect-cooling type)	11